

GLASS ETCH REPAIR KIT



Our glass polishing kit provides you the necessary tools to undo most glass etches. Cerium Oxide powder is the finest glass polishing compound available and when used with our felt bob, you will obtain the professional results you demand for your customers.

Kit Contains:

- 4 oz (by weight) tub of Cerium Oxide Powder
- 2" wide x 1" high felt bob, mounted on 1/4" shaft
- 2 crayons (for marking area)
- 1 sponge

Instructions:

1. To remove scratches that you cannot feel with your fingernail, mark them on the inside of the glass with a crayon or a piece of tape. Note: deeper scratches may not be possible to completely remove.
2. Mix a small quantity of Cerium Oxide powder with enough water to make a wet slurry.
3. Dip the flat bottom of the felt bob in slurry.
4. Mount the bob in the fastest electric drill available.
5. Using the FLAT bottom of the bob, (not the cylindrical sides), work the slurry up and down over the scratch until it is removed.
6. Keep the surface wet until completed. Do not allow slurry to dry out, or glass will become heated.

Felt Bob Cleaning Instructions:

Using 40-100 grit sandpaper, run the bob over the sandpaper until the bob looks clean. The felt bobs are intended to have only light to medium pressure to operate. Fast or high torque power systems may cause the felt to unbind from the shaft.